

Training duration

00:04:01

Number of photos tal

7

Number of defects m

0/4



Task completion rate

100%

Exceeding the safe dista

3

Inspection Report - Distribution network - 10kV Tension Pole

Serial number	Inspection location	Defect issue	Photo	performance evaluation
1	Full body of the pole			Correct
2	Pole number plate			Correct

Training duration

00:04:01

Number of photos tal

7

Number of defects m

0/4



Task completion rate

100%

Exceeding the safe dista

3

Inspection Report - Distribution network - 10kV Tension Pole

Serial number	Inspection location	Defect issue	Photo	performance evaluation
3	Base of the pole			Correct
4	Left pole top			Correct

Training duration

00:04:01

Number of photos tal

7

Number of defects m

0/4



Task completion rate

100%

Exceeding the safe dista

3

Inspection Report - Distribution network - 10kV Tension Pole

Serial number	Inspection location	Defect issue	Photo	performance evaluation
5	Pole top			Correct
6	Right pole top			Correct

Training duration

00:04:01

Number of photos tal

7

Number of defects m

0/4

Task completion rate

100%

Exceeding the safe dista

3

Inspection Report - Distribution network - 10kV Tension Pole

Serial number	Inspection location	Defect issue	Photo	performance evaluation
7	Large side span			Correct